

Input range	Eng. Units	Cal Pt	Upper	lower	Initial	Final	Sensitivity	STD	Unc.
							Check		
Source N	C	900	900.9	899.1	900.1	900.1	OK	1546	0.18
Source N	C	1300	1301.3	1298.7	1300.3	1300.3	OK	1546	0.18
Measure T	C	-200	-199.4	-200.6	-199.7	-199.7	OK	1546	0.74
Measure T	C	0	0.6	-0.6	-0.2	-0.2	OK	1546	0.73
Measure T	C	100	100.6	99.4	100	100	OK	1546	0.73
Measure T	C	200	200.6	199.4	199.8	199.8	OK	1546	0.73
Measure T	C	300	300.6	299.4	299.9	299.9	OK	1546	0.73
Measure T	C	400	400.6	399.6	400	400	OK	1546	0.73
Source T	C	-200	-199.4	-200.6	-200.1	-200.1	OK	1546	0.73
Source T	C	0	0.6	-0.6	-0.2	-0.2	OK	1546	0.33
Source T	C	100	100.6	99.4	100	100	OK	1546	0.33
Source T	C	200	200.6	199.4	200	200	OK	1546	0.33
Source T	C	300	300.6	299.4	300	300	OK	1546	0.33
Source T	C	400	400.6	399.6	400	400	OK	1546	0.33
Meas mVDC 0n 110 mv range	mDVC	0	0.017	-0.017	-0.002	-0.002	OK	1546	0.0033
		100	100.042	99.959	99.991	99.991	OK	1546	0.0033
		-100	-99.959	-100.042	-100.002	-100.002	OK	1546	0.0033
Meas VDC on 1.1 VDC range	VDC	0	0.00006	-0.00006	0	0	OK	1546	0.000033
		1	1.00031	0.9997	1	1	OK	1546	0.00045
Meas VDC on 11 VDC range	VDC	0	0.0006	-0.0006	0	0	OK	1546	0.000033
		10	10.0031	9.997	10.0002	10.0002	OK	1546	0.005
Meas mADC 30 mA range	mADC	4	4.0037	3.9963	3.997	3.997	OK	1546	0.0016
		20	20.0053	19.9947	19.998	19.998	OK	1546	0.0016
Resistance Measure 11 Ohm Range	Ohms	0	0.05	-0.05	0.01	0.01	OK	1546	0.042
11 ohm range	Ohms	10	10.055	9.945	10.01	10.01	OK	1546	0.025
110 Ohm range	Ohms	0	0.05	-0.05	0.01	0.01	OK	1546	0.042
110 Ohm range	Ohms	100	100.1	99.9	100	100	OK	1546	0.025
1100 Ohm range	Ohms	0	0.5	-0.5	0.01	0.01	OK	1546	0.042
1100 Ohm range	Ohms	1000	1001	999	999.9	999.9	OK	1546	0.34
Source mVDC	mVDC	100	100.0155	99.9845	100.004	100.004	OK	1205	0.01
	mVDC	120	120.067	119.933	120	120	OK	1205	0.062
		1000	1000.155	999.845	1000.03	1000.03	OK	1205	0.53
		14000	14002.15	13997.85	13999	13999	OK	1205	5.8
Source mADC	mADC	2	2.0035	1.9965	2.0003	2.0003	OK	1205	0.01
		4	4.0037	3.9963	4.0003	4.0003	OK	1205	0.01
		22	22.0055	21.9945	22.003	22.003	OK	1205	0.012
Resistanace source 11 Ohm range	Ohms	0.1	0.12	0.08	0.102	0.102	OK	1546	0.02
11 Ohm range	Ohms	1	1.0201	0.9799	1	1	OK	1546	0.02
11 ohm range	Ohms	10	10.021	9.979	9.999	9.999	OK	1546	0.02
110 ohm range	Ohms	20	20.042	19.958	20.002	20.002	OK	1546	0.02
110 ohm range	Ohms	100	100.05	99.95	99.996	99.996	OK	1546	0.02
1100 ohm range	Ohms	200	200.54	199.46	199.99	199.99	OK	1546	0.11
1100 ohm range	Ohms	1000	1000.7	999.3	999.9	999.9	OK	1546	0.11
11 kohm range	kohms	2	2.0056	1.9944	1.9999	1.9999	OK	1546	1.1
RTD meas. plt 100 (385) (27.096 Ohms)	Deg C	-180	-179.7	-180.3	-180	-180	OK	1546	0.63
4 wire 138.505 Ohms		100	100.5	99.5	99.9	99.9	OK	1546	0.049
RTD source plt 100 (385) 138.505 ohms	Deg C	100	100.5	99.5	100.002	100.002	OK	1546	0.049